



GYMS Inspection Report

Gymnasium Yearly Maintenance for Safety

SAMPLE REPORT

For illustration purposes only. Actual report content will vary based on the type, quantity, configuration, and condition of equipment inspected.

Property: Sample Community High School

Inspection Date: August 2026

Area Inspected: Main Gymnasium

Equipment Inspected: Six (6) ceiling-suspended basketball backstops and one (1) motorized divider curtain

Prepared By: Continental Partition Systems

Executive Summary

Continental Partition Systems inspected six basketball backstops and one motorized divider curtain to document current equipment condition, identify maintenance and repair needs, and provide recommended next steps.

Overall, the equipment inspected remains operational. Most mechanical, electrical, and support components were found to be in satisfactory condition. Several maintenance items were identified, including damaged backboard edge padding and a minor tear in the divider curtain vinyl.

No equipment was recommended for removal from service at the time of this sample inspection.



Inspection Summary

Equipment	Condition	Finding
Basketball Backstops	Good	Three backstops require maintenance items
Divider Curtain	Good	Minor vinyl damage should be monitored/repaired
Overall Gym Equipment	Good	Repairs recommended; equipment remains operational

Key Findings

- Hoisting cables, pulleys, winches, braces, and support components were satisfactory on the inspected backstops.
- Three backstops had damaged or missing protective edge padding.
- Safety hardware was identified for replacement on selected backstops.
- The divider curtain had a small tear in the lower vinyl.
- Recommended repairs can be addressed through planned service.

Basketball Backstops

Six ceiling-suspended basketball backstops were inspected.

Components Evaluated

The inspection may include review of:

- Winches
- Hoisting cables
- Pulleys



- Telescoping or sliding braces
- Folding brace hinges
- Structural fittings
- Support structure
- Backstop accessories
- Safety straps
- Goal and backboard hardware
- Mast assemblies
- Mast and brace hardware
- Electrical systems

Overall Backstop Condition

Most inspected components were found to be in satisfactory condition. Maintenance needs were limited to selected accessories and safety-related hardware.

Backstop	Overall Condition	Repair Needed
Northeast	Satisfactory	No
Northwest	Repair Recommended	Yes
West	Satisfactory	No
Southwest	Satisfactory	No
Southeast	Repair Recommended	Yes
East	Repair Recommended	Yes

Backstop Findings

Northwest Backstop

Condition: Repair Recommended

Observed

- Protective edge padding is torn and partially detached.
- Mechanical and structural components were satisfactory at the time of inspection.

Recommended Action

- Replace damaged edge padding.
- Replace associated safety hardware as required.

Photo Documentation

[Insert photo of damaged Northwest backstop edge pad]

Southeast Backstop

Condition: Repair Recommended

Observed

- Protective edge padding is ripped and partially missing.
- Remaining inspected components were satisfactory.

Recommended Action

- Replace damaged edge padding.
- Replace associated safety hardware as required.

Photo Documentation

[Insert photo of damaged Southeast backstop edge pad]

East Backstop

Condition: Repair Recommended

Observed

- Protective edge padding is broken.
- Remaining inspected components were satisfactory.

Recommended Action

- Replace damaged edge padding.
- Replace associated safety hardware as required.

Photo Documentation

[Insert photo of damaged East backstop edge pad]

Gym Divider Curtain

Type: Motorized Divider Curtain

Condition: Good — Monitor / Repair Recommended

The divider curtain was visually inspected for general condition and operation.

Components Evaluated

- Winch or drive components
 - Lineshaft
 - Lineshaft supports
 - Roller or bracket supports, where applicable
 - Curtain fabric
 - Support structure
-

- Concealed top and bottom components, where applicable
- Controls
- General operation

Finding

A small tear was observed in the lower portion of the curtain vinyl.

Recommended Action

- Monitor the damaged area for further tearing.
- Repair the vinyl before the damage becomes larger.

Photo Documentation

[Insert photo showing lower curtain tear]

Repair Priorities & Planning

The following items were identified during the inspection.

Attention Recommended

Backboard Edge Padding

- Replace damaged edge padding on the Northwest backstop.
- Replace damaged edge padding on the Southeast backstop.
- Replace damaged edge padding on the East backstop.

Safety Hardware

- Replace safety bolts and safety straps identified during the inspection.

Monitor / Planned Maintenance

Divider Curtain Vinyl

- Monitor the tear in the lower portion of the curtain.



- Schedule repair before the damaged area becomes larger.

Parts Identified

This sample inspection identified the following possible replacement items:

- Blue backboard edge pads
- Gray backboard edge pad
- Safety bolts
- Safety straps

Final quantities, compatibility, and availability are confirmed during repair quoting.

Repair Quote

Recommended repairs are quoted separately for review and approval before work proceeds.

Representative Photo Documentation

Photos are collected throughout the inspection to document equipment condition, inspected components, and areas needing attention.

Photo 1 — Overall Gym Equipment

Representative view of basketball backstops and divider curtain.

Photo 2 — Backstop Support & Folding Mechanism

Representative view of structural and folding components.

Photo 3 — Winch / Pulley Assembly

Representative view of mechanical operating components.

Photo 4 — Damaged Edge Padding

Example of a repair item identified during inspection.

Photo 5 — Divider Curtain Condition

Representative view of the curtain and identified fabric damage.

Photo 6 — Equipment Identification / Controls

Representative manufacturer, control, or equipment-identification documentation.

Additional technician photos may be included when needed to document specific equipment or findings.

Overall Assessment

The gym equipment inspected at this sample facility remains generally operational, with most mechanical, structural, and electrical components found to be in satisfactory condition.

The primary maintenance needs identified during the inspection involve damaged backboard edge padding, selected safety hardware, and minor divider curtain fabric damage.

Addressing the recommended repair items will help the facility maintain the equipment and reduce the likelihood of avoidable disruption.

Recommended Next Steps

1. Review the documented findings.
2. Review Continental Partition Systems' repair quote.
3. Approve the repairs you would like completed.
4. Schedule approved repair work.
5. Continue routine operational checks between inspections.
6. Plan the next annual GYMS inspection.

What Your GYMS Report May Include

Depending on the equipment inspected and conditions found, your report may include:

- Executive summary
 - Equipment inventory
 - Basketball backstop component findings
 - Divider curtain findings
 - Operational and safety observations
 - Individual equipment condition notes
 - Repair recommendations
 - Parts identified
 - Repair priorities
 - Photo documentation
 - Overall equipment assessment
 - Recommended next steps
-

About GYMS

GYMS — Gymnasium Yearly Maintenance for Safety — is Continental Partition Systems' proactive gym-equipment inspection program focused primarily on basketball backstops and divider curtains.

Keep Your Gym Ready.

[Request a GYMS Inspection](#)